

# Abram's Nation, LLC

4726 High Point Drive  
Gibsonia, PA 15044

# Repair Order

Date	R.O. No.
6/21/2022	7166

**THE SAFETY SLEEPER MUST  
BE WASHED BEFORE  
SHIPPING FOR REPAIR**

**(Repair items are inspected upon receipt. A \$25  
cleaning fee will be charged for unwashed repair  
items as determined by inspection)**

Ship To
Crystal Weishaupl 914 N Rock St, Minneapolis, KS 67467

SHIP YOUR RETURN TO:  
ABRAM'S NATION, LLC  
ATTN (ENTER RO#)  
4726 HIGH POINT DRIVE  
GIBSONIA, PA 15044

Rep	Original SO#	Client Name	Version	Size/Color
TD	831			Tw/Gy

Qty	U/M	Item	Description	Rate	Shipped	Serial #
		REPAIR00010	TSS, Side Door Zipper Replacement.	290.00		
		No Loaner	No Loaner required for repair	-30.00		

I understand that I am responsible for the cost of shipping my product to be repaired and for the shipping of The Safety Sleeper loaned product while my product is being repaired. If the repair falls w I also understand that the 1 year limited warranty only applies to my initial purchase of The Safety Sleeper and not for any repairs made during the 1 year limited warranty period.

PLEASE WASH YOUR SAFETY SLEEPER BEFORE RETURNING IT FOR REPAIR.

<b>Subtotal</b>	\$260.00
<b>Sales Tax (0.0%)</b>	\$0.00
<b>Total</b>	\$260.00

Signature \_\_\_\_\_

**PLEASE INCLUDE COVERLET WHEN SHIPPING BED TO BE REPAIRED**